

# Baler Rake Teeth

Fits for most any make or model



12

Per Pack

**Case IH, New Holland  
Baler Double Rake Teeth**  
**PN: 3894**

- Sold as a set of 12 rake teeth
- Double rake replacement teeth



10

Per Pack

**John Deere, Vermeer  
Baler Rake Teeth**  
**PN: 3892**

- Sold as a set of 10 rake teeth
- Replacement rake teeth
- Yoke opening: 1-5/8"
- Bolt hole diameter: 3/8"
- Tine length from mounting hole: 10"
- Tine diameter: 9/32"



12

Per Pack

**Massey Ferguson, Vermeer  
Baler Double Rake Teeth**  
**PN: 3893**

- Sold as a set of 12 rake teeth
- Double rake replacement teeth
- Yoke height: 1-3/8"
- Bolt hole diameter: 5/16"
- Tine length from bottom of yoke: 7-1/4"
- Tine diameter: 1/4"



10

Per Pack

**New Holland  
Baler Rake Teeth – LH**  
**PN: 3890**

- Sold as a set of 10 rake teeth
- Left hand replacement rake teeth
- Yoke opening: 1-55/64"
- Bolt hole diameter: 3/8"
- Tine length from mounting hole: 10"
- Tine diameter: 9/32"



10

Per Pack

**New Holland  
Baler Rake Teeth – RH**  
**PN: 3891**

- Sold as a set of 10 rake teeth
- Right hand replacement rake teeth
- Yoke opening: 1-55/64"
- Bolt hole diameter: 3/8"
- Tine length from mounting hole: 10"
- Tine diameter: 9/32"



10

Per Pack

**Universal  
Rake Teeth**  
**PN: 3889**

- Sold as a set of 10 rake teeth
- Replacement rake teeth
- Yoke opening: 1-11/16"
- Bolt hole diameter: 3/8"
- Tine length from mounting hole: 10"
- Tine diameter: 9/32"

See **REVERSE**  
for applications  
and part numbers.

- Heat treated tines for long lasting performance
- Consistent rubber quality assured by injection molding
- Hook style head for maximum rubber adhesion

TRACTORS&EATS.com



800-328-1752

308 NW 2nd Street • Renville, MN 56284



## Standard Applications

Tractor Make/Model	Part Number
<b>Case IH<sup>®</sup>, New Holland<sup>®</sup> Baler Double Rake Teeth</b>	
<b>Case IH<sup>®</sup> Balers:</b> LB333R, LB433R, LBX331R, LBX332R, LBX421R, LBX431R, LBX432R, RB454, RB464, RB564; <b>Case IH<sup>®</sup> Windrower Pick-up Header:</b> HDX20P (Replaces Case IH <sup>®</sup> OEM No. 9847572)  <b>New Holland<sup>®</sup> Balers:</b> 585, BB900, BB930AR, BB940R, BB940AR, BB960R, BB960AR, BB9050R, BB9060R, BB9070R, BB9080R, BR7060, BR7070, BR7080, BR7090; <b>New Holland<sup>®</sup> Windrower Pick-up Headers:</b> 27P, 270FP, 280FP, 290FP, 340W, 345W, 346W, 350W, 355W, 356W, 365W, 366W, 890W, 990W (Replaces New Holland <sup>®</sup> OEM NO. 89847572)	PN: 3894
<b>John Deere<sup>®</sup>, Vermeer<sup>®</sup> Baler Rake Teeth</b>	
<b>John Deere<sup>®</sup> Balers:</b> 700, 705 (Replaces John Deere <sup>®</sup> OEM No. AE56204); <b>Vermeer<sup>®</sup> Balers:</b> R-9, R-21, R-23, R-23A, R-24, R-24A (Replaces Vermeer <sup>®</sup> OEM No. 2888-001)	PN: 3892
<b>Massey Ferguson<sup>®</sup>, Vermeer<sup>®</sup> Baler Double Rake Teeth</b>	
<b>Massey Ferguson<sup>®</sup> Round Balers:</b> 1440, 1455, 1550, 1568 (Replaces Massey Ferguson <sup>®</sup> OEM No. 1059176M1); <b>Vermeer<sup>®</sup> Round Balers:</b> 5031, 504 Super I, 504H, 504I, 504I Silage, 504L, 505I, 505 Super I, 5005L, 5400 Rebel, 5410 Rebel, 5500 Rebel, 554XL, 555XL, 604J, 604K, 604XL, 605H, 605J, 605 Super J, 605K, 605L, 605XL (Replaces Vermeer <sup>®</sup> OEM No. 27997-001)	PN: 3893
<b>New Holland<sup>®</sup> Baler Rake Teeth - LH</b>	
<b>New Holland<sup>®</sup> Balers:</b> 216, 258 with left hand hook, 259 Rolabar Rake (Replaces New Holland <sup>®</sup> OEM Nos. 65668, 850613); <b>Allen Models:</b> Left Hand Rakes	PN: 3890
<b>New Holland<sup>®</sup> Baler Rake Teeth - RH</b>	
<b>New Holland<sup>®</sup> Balers:</b> 216, 258 with right hand hook, 259 Rolabar Rake (Replaces New Holland <sup>®</sup> OEM Nos. 139041, 850614); <b>Allen Models:</b> Right Hand Rakes	PN: 3891
<b>Universal Double Rake Teeth</b>	
<b>Fits most round bar and parallel bar rakes with 1-5/8" bar.</b>  <b>John Deere<sup>®</sup> Balers:</b> 54, 64, 74, 350, 350A, 640, 650, 652, 660, 662, 670, 671, 673, 851, 858A*, 894, 894A*, 896*, 896A; <i>*Not for use on models with Vertical Mounting Studs</i> (Replaces John Deere <sup>®</sup> OEM Nos. AE24953, AE47389)  <b>New Holland<sup>®</sup> Balers:</b> 55, 56, 57, 256 (Replaces New Holland <sup>®</sup> OEM Nos. 65609, 850612)  <b>Allis Chalmers<sup>®</sup>, AGCO<sup>®</sup>, IHC<sup>®</sup>, New Idea<sup>®</sup> and many other baler models</b>	PN: 3889